

To: AUTHORISED DEALERS/DISTRIBUTORS
 N.Z. APPROVED INSTALLERS
 H.O., REG'L & AUST. MANAGERS
 APPLIC. NOTICE GENERAL LIST

Issue No.: 03/01
 Date: 25th June 2001
 From: C Snell/K Edwards

Subject: HAN L5 CONTROLLER (058V2)
 Units: OSA/ISD220, also applies if used with OSA/ISD250-390

It is important on these unit combinations to remove the jumper (on the relay board) marked SK.

Failure to do so could result in the capacitors on the HAN-L5 relay board holding in speed relays such that the motor is being fed power on more than one speed tapping.

This could result in motor burn out.

We suggest that you make notes on the Application Note 02/01 DATA SHEET fig. 3 and fig. 7. See attached.

