

To: AUTHORISED DEALERS/DISTRIBUTORS
N.Z. APPROVED INSTALLERS
H.O., REG'L & AUST. MANAGERS
APPLIC. NOTICE GENERAL LIST

Issue No.: 02/10
Date: 1st September 2010
From: T King

Subject: DELAY TIMER REPLACEMENT
Units: VARIOUS OLD OBSOLETE MODELS

We have discontinued buying the Everwell Time Delay (our part number 012 000 750).

Our stock is now exhausted, so the best we can offer as a replacement is the MARS Time Delay model DOB32392 which is our new part number 012 000 749.

Unfortunately it is not a like for like drop in replacement, the number of terminals is different, 3 pins instead of 4, and the wiring detail is not the same.

The wiring of the replacement is relatively easy and the attached wiring diagram TOK-000-208 shows this clearly.